

HT730 How to goes to Android Recovery Menu

1. Press and hold the power key + P1 key for 15 seconds until you see the Android Logo.
2. Android Recovery menu appearance.
3. Goes to wipe data/factory reset

